

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/23	MAKE	HITACHI	MODEL	EX120-3
SERIAL	12V-41281		STAMP	12V-41281	
HR METER	8513	HR	YEAR	1994	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	にじみあり OIL OOZING
Blow-By	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Oil	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Exhaust Color	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
US EPA	YES · <input checked="" type="radio"/> NO <input type="radio"/>	
MAIN PUMP		
Sound	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Oil leakage	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Power	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
COOLING SYSTEM		
Radiator	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Oil Cooler	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
OPERATING SYSTEM		
Swing	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	ガタあり SWING: LOOSE
Travel	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Inside Cover	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	破れ小 HOLE
Glasses	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Boom Cylinder	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	
Arm	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	前面と背面に鉄板溶接あり WELDED
Arm Cylinder	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	にじみあり OIL OOZING
BKT	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	バケット周りのピンガタ大 PIN: MUCH LOOSE
BKT Cylinder	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR <input checked="" type="radio"/> · Attn <input checked="" type="radio"/>
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。