

**INSPECTION SHEET 検品書
EXCAVATOR バックホー**

INSPECTION DATE	2024/10/1	MAKE	CAT	MODEL	320E-2
SERIAL	CAT0320EHSXE02671		STAMP	CAT0320EHSXE02671	
HR METER	4805 / 4830	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	破れあり HUGE CUT
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
<div style="border: 1px solid black; padding: 5px;">BKT STD (SLOPE) NARROW / SKELETON / OTHER ()</div> <div style="border: 1px solid black; padding: 5px;">Lever LONG · WRIST</div> <div style="border: 1px solid black; padding: 5px;">Multi MULTI · 2 · NO</div> <div style="border: 1px solid black; padding: 5px;">ARM-CRANE YES · NO</div> <div style="border: 1px solid black; padding: 5px;">BLADE YES · NO</div> <div style="border: 1px solid black; padding: 5px;">OFFSET YES · NO</div> <div style="border: 1px solid black; padding: 5px;">OFFSET Cylinder FAIR · Attn</div> <div style="border: 1px solid black; padding: 5px;">Piping YES · NO Breaker only · Multi</div>	
COMMENT	
<div style="border: 1px solid black; padding: 5px;">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</div>	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。