

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/16	MAKE	SUMITOMO	MODEL	SH200LC-3
SERIAL	NO PLATE		STAMP	200L3-1206	
HR METER	12749	HR	YEAR	2003	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	穴あり HOLES
Inside Cover	FAIR · Attn	*1
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*2
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	油漏れあり OIL LEAKING
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER (MAGNET)
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
A/Cあるが冷風が出ない A/C: NOT BLOWING AIR	
エレベータ動かない ELEVATOR CAB: NOT WORKING	
エレベータの下より油漏れあり LOWER PART OF ELEVATOR: OIL LEAKING	
*1 ドアノブ周り欠、ドア内張り破れあり	
*1 INSIDE COVER OF AROUND DOOR KNOB: MISSING, INSIDE COVER OF DOOR: CUTS	
*2 左側油漏れ小、右側にじみあり	
*2 LEFT CYLINDER: OIL LEAKING, RIGHT CYLINDER: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。