

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/18	MAKE	KOMATSU	MODEL	PC228US-10
SERIAL	1362		STAMP	KMTPC250VEC001362	
HR METER	UNREADABLE	HR	YEAR	2014	YR
CAB/CNP	<input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE		2014	600G	

ENGINE : MODEL		S/N	UNDERCARRIAGE : See Photos. 写真参照		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	COMMENT		
Sound	<input checked="" type="radio"/> FAIR · Attn			
Oil	<input checked="" type="radio"/> FAIR · Attn			
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn			
US EPA	<input checked="" type="radio"/> YES · NO			
MAIN PUMP			BKT <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()		
Sound	<input checked="" type="radio"/> FAIR · Attn		Lever	LONG · <input checked="" type="radio"/> WRIST	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		Multi	MULTI · 2 · <input checked="" type="radio"/> NO	
Power	<input checked="" type="radio"/> FAIR · Attn		ARM-CRANE	YES · <input checked="" type="radio"/> NO	
COOLING SYSTEM			BLADE	YES · <input checked="" type="radio"/> NO	
Radiator	<input checked="" type="radio"/> FAIR · Attn		OFFSET	YES · <input checked="" type="radio"/> NO	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		OFFSET Cylinder	FAIR · Attn	
OPERATING SYSTEM			Piping	<input checked="" type="radio"/> YES · NO Breaker only <input checked="" type="radio"/> Multi	
Swing	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	旋回時異音あり NOISES	COMMENT		
Travel	<input checked="" type="radio"/> FAIR · Attn		モニター見えない MONITOR: UNREADABLE		
INTERIOR See Photos. 写真参照			*1 ブームシリンダーの取付け部辺り溶接あり(写真参照) WELDED		
Operator's Seat	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	破れ小 CUT		
Inside Cover	<input checked="" type="radio"/> FAIR · Attn			
Glasses	<input checked="" type="radio"/> FAIR · Attn			
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	*1		
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn			
Arm	<input checked="" type="radio"/> FAIR · Attn			
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn			
BKT	<input checked="" type="radio"/> FAIR · Attn			
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn			
			RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。