

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/10/16	MAKE	KOMATSU	MODEL	D51PX-22
SERIAL	B11605		STAMP	KMT0D080H51B11605	
HR METER	8314	HR	SHOE	720LGP	YEAR 2009 YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL	S/N
Oil leakage <input type="radio"/> FAIR · Attn	
Blow-By <input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound <input type="radio"/> FAIR · Attn	
Oil <input type="radio"/> FAIR · Attn	
Exhaust Color <input type="radio"/> FAIR · Attn	
US EPA <input type="radio"/> YES · NO	
OPERATION PUMP	
Sound <input type="radio"/> FAIR · Attn	
Oil leakage <input type="radio"/> FAIR · Attn	
Power <input type="radio"/> FAIR · Attn	
COOLING SYSTEM	
Radiator <input type="radio"/> FAIR · Attn	
Oil Cooler <input type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL	
T/M TYPE <input type="radio"/> PS · DD	DIFF. STEERING YES · <input type="radio"/> NO
Transmission <input type="radio"/> FAIR · Attn	
Travel <input type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照	
Operator's Seat <input type="radio"/> FAIR · Attn	
Inside Cover <input type="radio"/> FAIR · Attn	
Glasses <input type="radio"/> FAIR · Attn	
AirCon <input type="radio"/> A/C · H/C · H only · C only · None	
BLADE & CYLINDERS	
BLADE <input type="radio"/> FAIR · Attn	
CYLD.(R) <input type="radio"/> FAIR · Attn	
CYLD.(L) <input type="radio"/> FAIR · Attn	
TILT CYLD <input type="radio"/> FAIR · Attn	ガタあり LOOSE
ANGLE CYLD <input type="radio"/> FAIR · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input type="radio"/> FAIR · Attn		
EQUALIZER BAR	<input type="radio"/> FAIR · Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。