

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2024/10/8	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE			
MAKE	KATO		MODEL	NK70M		
SERIAL	762708		STAMP	FD161B-10578		
HR METER	UNKNOWN	HR	Odometer	21421 km	YEAR	YR
CHASSIS	MODEL	FD161B	No.	10578	TIRE	7.50R16

ENGINE(CRANE) : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
ENGINE(CHASSIS) : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn	白煙あり WHITE FUMES	
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG		
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	AT · MT	No. OF GEARS	5 GEARS
Transmission	FAIR · Attn		
No. of DRIVE WHEELS	2 WD		
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR · Attn	破れ大 BROKEN, HUGE CUTS	
Inside Cover	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · NONE		

CRANE	
WEIGHT	1
HOOK	4.9t, BALL
BOOM	
MAIN BOOM	
BOOM TOTAL	
No. of Section	3 SECTIONS
TOP SHEAVE	YES · NO
JIB	STD · PWR
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
COMMENT	
CAB、ブーム：腐食、穴多数あり	
CAB & BOOM: CORRODED & MUCH HUGE HOLES	
ヘコミ多数あり DEFORMED	
作動油タンクヘコミ大 HYDRAULIC OIL TANK: MUCH DENT	
クレーン部CABドアヘコミ大 DOOR OF CRANE CAB: MUCH DENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。