

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/4/4	MAKE	YANMAR	MODEL	VIO45-6
SERIAL	60711		STAMP	60711	
HR METER	3581	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	350G PADS	

<b>ENGINE : MODEL</b>		S/N	P9065
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE *1	
Sound	FAIR · Attn	*1	
Oil	<u>FAIR</u> · Attn		
Exhaust Color	FAIR · Attn	*1	
US EPA	YES · <u>NO</u>		
<b>MAIN PUMP</b>			
Sound	FAIR · Attn	*1	
Oil leakage	FAIR · Attn	*1	
Power	FAIR · Attn	*1	
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>OPERATING SYSTEM</b>			
Swing	FAIR · Attn	*1	
Travel	FAIR · Attn	*1	
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<u>FAIR</u> · Attn		
Inside Cover	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
<b>BOOM / ARM / BKT</b>			
Boom	<u>FAIR</u> · Attn		
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn		
Arm Cylinder	<u>FAIR</u> · Attn		
BKT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	<u>YES</u> · NO
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
<b>COMMENT</b>	
モニターエラー表示あり、E/G始動不可	
WARNING DISPLAY, UNABLE TO START THE ENGINE	
*1 未確認 NOT CHECKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。