

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/10/16	MAKE	KOMATSU	MODEL	D31PX-22
SERIAL	60350		STAMP	KMT0D111E01060350	
HR METER	5179	HR	SHOE	600LGP	YEAR 2008 YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE	

ENGINE : MODEL 4D95LE-5 S/N 506623	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	<input checked="" type="radio"/> YES · NO
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<input checked="" type="radio"/> PS · DD DIFF. STEERING YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None
BLADE & CYLINDERS	
BLADE	<input checked="" type="radio"/> FAIR · Attn
CYLD.(R)	<input checked="" type="radio"/> FAIR · Attn
CYLD.(L)	<input checked="" type="radio"/> FAIR · Attn
TILT CYLD	<input checked="" type="radio"/> FAIR · Attn
ANGLE CYLD	<input checked="" type="radio"/> FAIR · Attn

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input checked="" type="radio"/> FAIR · Attn		
EQUALIZER BAR	<input checked="" type="radio"/> FAIR · Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。