

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/10/16	MAKE	SAKAI	MODEL	T2
SERIAL	53214			STAMP	TT1-53214
HR METER	3110	HR	Odometer	8701	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE			TIRE SIZE	14/70-20

ENGINE : MODEL	S/N
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	YES · <u>NO</u>
OPERATION PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · <u>DD</u>
Transmission	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
FOOT BRAKE	<u>FAIR</u> · Attn
PARKING BRAKE	<u>FAIR</u> · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn
Inside Cover	<u>FAIR</u> · Attn
Glasses	<u>FAIR</u> · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>
OTHERS	
Vibratory	<u>FAIR</u> · Attn
Watering	<u>FAIR</u> · <u>Attn</u> *1
Articulate	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
ブレーキ: エア溜まりにくい(エア漏れ?)	
AIR FOR BRAKE: HARD TO STORE (AIR LEAKING?)	
*1 タイヤ散水不良、ホース切れあり	
*1 WATERING TO TIRES: MALFUNCTION, HOSE: CUT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。