

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/17	MAKE	HITACHI	MODEL	ZX225US-5B
SERIAL	HCMDCNA0V00301168		STAMP	HCMDCNA0V00301168	
HR METER	9625	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	SHOE		790G	

ENGINE : MODEL 4HK1 S/N 717424	
Oil leakage	<u>FAIR</u> · Attn
Blow-By	<u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn
Oil	<u>FAIR</u> · Attn
Exhaust Color	<u>FAIR</u> · Attn
US EPA	<u>YES</u> · NO
MAIN PUMP	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn
OPERATING SYSTEM	
Swing	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn
Inside Cover	<u>FAIR</u> · Attn
Glasses	<u>FAIR</u> · Attn
AirCon	<u>A/C</u> · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	<u>FAIR</u> · Attn
Boom Cylinder	<u>FAIR</u> · <u>Attn</u> 左側油漏れ小 LEFT CYLINDER: OIL LEAKING
Arm	<u>FAIR</u> · Attn
Arm Cylinder	<u>FAIR</u> · Attn
BKT	<u>FAIR</u> · Attn
BKT Cylinder	<u>FAIR</u> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	<u>YES</u> · NO
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。