

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/7	MAKE	CAT	MODEL	312D
SERIAL	CAT0312DAFBJ03094		STAMP	CAT0312DAFBJ03094	
HR METER	5960 / 5963	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	500G PADS		

ENGINE : MODEL	S/N
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Blow-By <input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO
MAIN PUMP	
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Power <input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM	
Radiator <input checked="" type="radio"/> FAIR · Attn	
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM	
Swing <input checked="" type="radio"/> FAIR · Attn	
Travel <input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照	
Operator's Seat <input checked="" type="radio"/> FAIR · Attn	
Inside Cover <input checked="" type="radio"/> FAIR · Attn	
Glasses <input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom <input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder <input checked="" type="radio"/> FAIR · Attn	
Arm <input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder <input checked="" type="radio"/> FAIR · Attn	
BKT <input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder <input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
COMMENT	
バックモニター不鮮明 BACK MONITOR: BLURRED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。