

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/25	MAKE	HITACHI	MODEL	ZX225USRE-3
SERIAL	HCMDCCA0T00220457		STAMP	HCMDCCA0T00220457	
HR METER	13467	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <input checked="" type="radio"/> CAB /	ROPS CNP /	CNP /	NONE	SHOE 600G

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Exhaust Color	<input type="radio"/> FAIR · <input type="radio"/> Attn	
US EPA	<input type="radio"/> YES · <input type="radio"/> NO	
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Power	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil Cooler	<input type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Travel	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Inside Cover	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Glasses	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C	<input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Arm	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
BKT	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / <input checked="" type="radio"/> OTHER / FORK GRAB)
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · <input type="radio"/> Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
EV仕様 ELECTRIC VEHICLE	
付属品: 発電機 GENERATOR AS SPARE	
MAKE: DENYO DCA-150ESK-3865881	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。