

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/23	MAKE	KOMATSU	MODEL	PC78UU-8
SERIAL	18499		STAMP	KMTPC213J01018499	
HR METER	5185	HR	YEAR	2012	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

**ENGINE : MODEL S/N**

Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	<input checked="" type="radio"/> YES · NO	

**MAIN PUMP**

Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	

**COOLING SYSTEM**

Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	

**OPERATING SYSTEM**

Swing	<input checked="" type="radio"/> FAIR · Attn	ガタあり SWING: LOOSE
Travel	<input checked="" type="radio"/> FAIR · Attn	

**INTERIOR See Photos. 写真参照**

Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	

**BOOM / ARM / BKT**

Boom	<input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn	
Arm	<input checked="" type="radio"/> FAIR · Attn	ガタあり LOOSE
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn	
BKT	<input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn	

**UNDERCARRIAGE : See Photos. 写真参照**

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

**COMMENT**

シューパッド剥がれ多数あり MANY RUBBER PADS: PEELED OFF

BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )
-----	--

Lever	LONG · <input checked="" type="radio"/> WRIST
-------	---

Multi	MULTI · 2 · <input checked="" type="radio"/> NO
-------	---

ARM-CRANE	<input checked="" type="radio"/> YES · NO
-----------	---

BLADE	<input checked="" type="radio"/> YES · NO
-------	---

OFFSET	<input checked="" type="radio"/> YES · NO	ガタあり LOOSE
--------	---	------------

OFFSET Cylinder	<input checked="" type="radio"/> FAIR · Attn
-----------------	--

Piping	YES · <input checked="" type="radio"/> NO	Breaker only · Multi
--------	---	----------------------

**COMMENT**

CABドア開閉しづらい DOOR: HARD TO OPEN & CLOSE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。