INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/23	MAKE	KATO	MODEL	KR-10H-L Ⅱ
SERIAL No.	PLATE : 3910589		STAMP : KR102-0589		
HR METER	16945 HR		Odometer	110273 km	
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL W04C S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Computer	OK NG	*1
Swing	FAIR・Attn	
Travel	FAIR・Attn	
TRANSMISSION		
Transmission	FAIR・Attn	
No. OF GEARS	– GEARS	
No, of DRIVE WHEELS	4 WD	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR・Attn	
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
COMMENT		

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	FAIR・Attn	
DERRICKING CYL.	FAIR・Attn	にじみあり OIL OOZING
EXTENSION CYL.	FAIR・Attn	
JIB	YES・NO	
JIB TYPE	STD・PWR	
MAIN & SUB WIRE	YES・NO	
HOOK	10t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
OUTRIGGERS		
OUTRIGGERS	X・H	
OUTRIGGERS COND.	FAIR・Attn	
COMMENT		
燃料計故障あり FUEL GAUGE: MALFUNCTION		
*1 パネル表示不良 PANEL: MALFUNCTION TO DISPLAY		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。