

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2024/10/15	MAKE	MAEDA	MODEL	CC1485S-1
SERIAL No.	PLATE : 7775		STAMP	7775	
HR METER	1274	HR	SHOE	500G PADS	YEAR YR

<b>ENGINE : MODEL</b> 4LE2		<b>S/N</b> 698729	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
<b>OPERATION PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
<b>OPERATING SYSTEM</b>			
Computer	<input checked="" type="radio"/> OK · NG		
Swing	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
<b>BOOM</b>			
MAIN BOOM			
BOOM TOTAL			
TOP SHEAVE	YES · <input checked="" type="radio"/> NO		
JIB			
TOWER			

<b>INTERIOR</b> See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
WEIGHT	-
HOOK	4.9t
LIFTER	YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>	
CAB	
5段ブーム 5-SECTION BOOM	
EPA	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。