

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/11	MAKE	CAT	MODEL	308E
SERIAL	CAT0308EJHEL00516		STAMP	CAT0308EJHEL00516	
HR METER	5213	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
MAIN PUMP		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Swing	<input type="radio"/> FAIR · Attn	ガタあり SWING: LOOSE
Travel	<input type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	F割れあり UPPER WINDSHIELD: CRACKED
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
BOOM / ARM / BKT		
Boom	<input type="radio"/> FAIR · Attn	ガタあり LOOSE
Boom Cylinder	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	油漏れあり OIL LEAKING
Arm	<input type="radio"/> FAIR · Attn	ガタあり LOOSE
Arm Cylinder	<input type="radio"/> FAIR · Attn	
BKT	<input type="radio"/> FAIR · Attn	
BKT Cylinder	<input type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
シューパッド:カスが付いているだけ RUBBER PADS: ALMOST GONE		
BKT	<input type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ()	
Lever	LONG · <input checked="" type="radio"/> WRIST	
Multi	<input type="radio"/> MULTI · 2 · NO	
ARM-CRANE	YES · <input checked="" type="radio"/> NO	
BLADE	<input type="radio"/> YES · NO	
OFFSET	YES · <input checked="" type="radio"/> NO	
OFFSET Cylinder	FAIR · Attn	
Piping	<input type="radio"/> YES · NO	Breaker only · <input checked="" type="radio"/> Multi
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。