

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/11	MAKE	HITACHI	MODEL	ZX350K-5B
SERIAL	HCMDDDA4H00071288			STAMP	HCMDDDA4H00071288
HR METER	8223	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil	<input checked="" type="radio"/> FAIR	Attn
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn
US EPA	YES	<input checked="" type="radio"/> NO
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Power	<input checked="" type="radio"/> FAIR	Attn
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR	Attn
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR	Attn
Travel	<input checked="" type="radio"/> FAIR	Attn
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn
Inside Cover	<input checked="" type="radio"/> FAIR	Attn
Glasses	<input checked="" type="radio"/> FAIR	Attn
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR	Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn
Arm	<input checked="" type="radio"/> FAIR	Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR	<input checked="" type="radio"/> Attn 油漏れ小 OIL LEAKING
BKT	<input checked="" type="radio"/> FAIR	Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER()	
Lever	LONG	<input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI	<input type="radio"/> 2 · <input type="radio"/> NO
ARM-CRANE	YES	<input checked="" type="radio"/> NO
BLADE	YES	<input checked="" type="radio"/> NO
OFFSET	YES	<input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR	Attn
Piping	<input checked="" type="radio"/> YES · <input type="radio"/> NO	Breaker only <input checked="" type="radio"/> Multi
COMMENT		
左サイドカバーラッチ掛からない LEFT SIDE COVER LATCH: NOT WORKING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。