

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/7	MAKE	HITACHI	MODEL	ZX330-5B
SERIAL	HCMDDDA0C00071461		STAMP	HCMDDDA0C00071461	
HR METER	3912	HR	YEAR	YR	
CAB/CNP	<input checked="" type="radio"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL	S/N
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Blow-By <input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO
MAIN PUMP	
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Power <input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM	
Radiator <input checked="" type="radio"/> FAIR · Attn	
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM	
Swing <input checked="" type="radio"/> FAIR · Attn	
Travel <input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照	
Operator's Seat <input checked="" type="radio"/> FAIR · Attn	
Inside Cover <input checked="" type="radio"/> FAIR · Attn	
Glasses <input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom <input checked="" type="radio"/> FAIR · Attn	
Boom Cylinder <input checked="" type="radio"/> FAIR · Attn	
Arm <input checked="" type="radio"/> FAIR · Attn	
Arm Cylinder <input checked="" type="radio"/> FAIR · Attn	
BKT <input checked="" type="radio"/> FAIR · Attn	
BKT Cylinder <input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。