

INSPECTION SHEET 検品書
EXCAVATOR バックホー

| | | | | | |
|-----------------|--|------|-----------|-------|-------------------|
| INSPECTION DATE | 2024/10/4 | MAKE | CAT | MODEL | 308D |
| SERIAL | CAT0308DKHSA00114 | | | STAMP | CAT0308DKHSA00114 |
| HR METER | 5047 / UNKNOWN | HR | YEAR | YR | |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | SHOE | 450G PADS | | |

| | | |
|----------------------------------|------------------------------------|---------------------------------|
| ENGINE : MODEL | | S/N |
| Oil leakage | FAIR · Attn | |
| Blow-By | FAIR · Attn | A LITTLE · MIDDLE · SEVERE |
| Sound | FAIR · Attn | |
| Oil | FAIR · Attn | |
| Exhaust Color | FAIR · Attn | |
| US EPA | YES · NO | |
| MAIN PUMP | | |
| Sound | FAIR · Attn | |
| Oil leakage | FAIR · Attn | |
| Power | FAIR · Attn | |
| COOLING SYSTEM | | |
| Radiator | FAIR · Attn | |
| Oil Cooler | FAIR · Attn | |
| OPERATING SYSTEM | | |
| Swing | FAIR · Attn | ガタあり SWING: LOOSE |
| Travel | FAIR · Attn | |
| INTERIOR See Photos. 写真参照 | | |
| Operator's Seat | FAIR · Attn | |
| Inside Cover | FAIR · Attn | |
| Glasses | FAIR · Attn | F割れあり UPPER WINDSHIELD: CRACKED |
| AirCon | A/C · H/C · H only · C only · None | |
| BOOM / ARM / BKT | | |
| Boom | FAIR · Attn | |
| Boom Cylinder | FAIR · Attn | |
| Arm | FAIR · Attn | ガタあり LOOSE |
| Arm Cylinder | FAIR · Attn | |
| BKT | FAIR · Attn | ガタあり LOOSE |
| BKT Cylinder | FAIR · Attn | |

| | |
|---|---|
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| COMMENT | |
| | |
| BKT | STD / SLOPE / NARROW / SKELETON / OTHER () |
| Lever | LONG · WRIST |
| Multi | MULTI · 2 · NO |
| ARM-CRANE | YES · NO |
| BLADE | YES · NO |
| OFFSET | YES · NO |
| OFFSET Cylinder | FAIR · Attn |
| Piping | YES · NO Breaker only Multi |
| COMMENT | |
| 下側HRメーター読み取り不可 LOWER HR METER: MALFUNCTION | |
| CAB上部ハッチ変形あり EVACUATION HATCH AT CEILING: DISTORTED | |
| CABドアラッチかからない DOOR LATCH: MALFUNCTION | |
| マフラー破損あり MUFFLER: BROKEN | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。