

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/3	MAKE	CAT	MODEL	313DCR
SERIAL	CAT0313DCLCE00458		STAMP	CAT0313DCLCE00458	
HR METER	7095	HR	YEAR	YR	
CAB/CNP	ROPS CAB (CAB) ROPS CNP / CNP / NONE		SHOE	500G	

<b>ENGINE : MODEL</b> C4.2 <b>S/N</b>	
Oil leakage	(FAIR) · Attn
Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn
Oil	(FAIR) · Attn
Exhaust Color	(FAIR) · Attn
US EPA	(YES) · NO
<b>MAIN PUMP</b>	
Sound	(FAIR) · Attn
Oil leakage	(FAIR) · Attn
Power	(FAIR) · Attn
<b>COOLING SYSTEM</b>	
Radiator	(FAIR) · Attn
Oil Cooler	(FAIR) · Attn
<b>OPERATING SYSTEM</b>	
Swing	(FAIR) · Attn ガタあり SWING: LOOSE
Travel	(FAIR) · Attn
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	(FAIR) · Attn
Inside Cover	(FAIR) · Attn
Glasses	(FAIR) · Attn
AirCon	(A/C) · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	(FAIR) · Attn
Boom Cylinder	(FAIR) · Attn
Arm	(FAIR) · Attn ガタあり LOOSE
Arm Cylinder	(FAIR) · Attn
BKT	(FAIR) · Attn
BKT Cylinder	(FAIR) · Attn

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
BKT (STD) / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG · (WRIST)
Multi	(MULTI) · 2 · NO
ARM-CRANE	(YES) · NO
BLADE	YES · (NO)
OFFSET	YES · (NO)
OFFSET Cylinder	FAIR · Attn
Piping	(YES) · NO Breaker only · (Multi)
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。