

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/25	MAKE	SUMITOMO	MODEL	SH75X-6A
SERIAL	SMT075X6P00BB7141		STAMP	SMT075X6P00BB7141	
HR METER	1292	HR	YEAR	2019	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G	

ENGINE :	MODEL	4LE2	S/N	813912
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
<b>MAIN PUMP</b>				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
<b>COOLING SYSTEM</b>				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
<b>OPERATING SYSTEM</b>				
Swing	FAIR · Attn			
Travel	FAIR · Attn			
<b>INTERIOR      See Photos. 写真参照</b>				
Operator's Seat	FAIR · Attn			
Inside Cover	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
<b>BOOM / ARM / BKT</b>				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
BKT	FAIR · Attn			
BKT Cylinder	FAIR · Attn			

<b>UNDERCARRIAGE :</b>						<b>See Photos.</b>							<b>写真参照</b>										
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																			4				
<b>COMMENT</b>																							
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER( )																					
Lever	LONG ▪	(WRIST)																					
Multi	MULTI ▪ 2 ▪	(NO)																					
ARM-CRANE	(YES) ▪ NO																						
BLADE	(YES) ▪ NO																						
OFFSET	YES ▪ (NO)																						
OFFSET Cylinder	FAIR ▪ Attn																						
Piping	(YES) ▪ NO	Breaker only ▪ Multi																					
<b>COMMENT</b>																							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																			4				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。