

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2024/10/25	MAKE	MOROOKA	MODEL	MST-200VDR
SERIAL	20R109		STAMP	20R109	
HR METER	313	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	300R	TIRE

ENGINE : MODEL V1505		S/N 1JT6514	
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	<u>YES</u> · NO		
OPERATION PUMP			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<u>PS</u> · DD	No. OF GEARS	2 GEARS
Transmission	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
Swing	<u>FAIR</u> · Attn		
Articulate	<u>FAIR</u> · Attn		
FOOT BRAKE	<u>FAIR</u> · Attn		
PARKING BRAKE	<u>FAIR</u> · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	<u>FAIR</u> · Attn		
Inside Cover	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		

MAIN FRAME	
MAIN FLAME	<u>FAIR</u> · Attn
VESSEL	
VESSEL	<u>FAIR</u> · Attn
REAR GATE TYPE	<u>NORMAL</u> · L-GATE (FLAT)
REAR GATE	<u>FAIR</u> · Attn
UNDERCARRIAGE: See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。