

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/18	MAKE	KOBELCO	MODEL	SK135SR-5
SERIAL	YY08-33018			STAMP	YY08-33018
HR METER	4482	HR	YEAR	2018	YR
CAB/CNP	<input checked="" type="checkbox"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL	4JJ1	S/N
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn	
Blow-By	<input checked="" type="checkbox"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="checkbox"/> FAIR · Attn	
Oil	<input checked="" type="checkbox"/> FAIR · Attn	
Exhaust Color	<input checked="" type="checkbox"/> FAIR · Attn	
US EPA	<input checked="" type="checkbox"/> YES · NO	
MAIN PUMP		
Sound	<input checked="" type="checkbox"/> FAIR · Attn	
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn	
Power	<input checked="" type="checkbox"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="checkbox"/> FAIR · Attn	
Oil Cooler	<input checked="" type="checkbox"/> FAIR · Attn	
OPERATING SYSTEM		
Swing	<input checked="" type="checkbox"/> FAIR · Attn	
Travel	<input checked="" type="checkbox"/> FAIR · Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	<input checked="" type="checkbox"/> FAIR · Attn	
Inside Cover	<input checked="" type="checkbox"/> FAIR · Attn	
Glasses	<input checked="" type="checkbox"/> FAIR · Attn	
AirCon	<input checked="" type="checkbox"/> A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<input checked="" type="checkbox"/> FAIR · Attn	
Boom Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	
Arm	<input checked="" type="checkbox"/> FAIR · Attn	
Arm Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	
BKT	<input checked="" type="checkbox"/> FAIR · Attn	
BKT Cylinder	<input checked="" type="checkbox"/> FAIR · Attn	

UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	
COMMENT		
BKT	<input checked="" type="checkbox"/> STD / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG · <input checked="" type="checkbox"/> WRIST	
Multi	<input checked="" type="checkbox"/> MULTI · 2 · NO	
ARM-CRANE	<input checked="" type="checkbox"/> YES · NO	
BLADE	YES · <input checked="" type="checkbox"/> NO	
OFFSET	YES · <input checked="" type="checkbox"/> NO	
OFFSET Cylinder	FAIR · Attn	
Piping	<input checked="" type="checkbox"/> YES · NO	Breaker only <input checked="" type="checkbox"/> Multi
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。