

**INSPECTION SHEET 検品書
EXCAVATOR バックホー**

INSPECTION DATE	2024/10/22	MAKE	YANMAR	MODEL	VIO30-6
SERIAL	6K247		STAMP	6K247	
HR METER	1194	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL	S/N		158402
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES · <input checked="" type="radio"/> NO		
MAIN PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
OPERATING SYSTEM			
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	· H/C · H only · C only · None	
BOOM / ARM / BKT			
Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
BKT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	<input checked="" type="radio"/> FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only <input checked="" type="radio"/> Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。