

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/23	MAKE	YANMAR	MODEL	VIO30-6
SERIAL	6K264		STAMP	6K264	
HR METER	1000	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G PADS	

ENGINE : MODEL		S/N	158568
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES	<input checked="" type="radio"/> NO	
MAIN PUMP			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
OPERATING SYSTEM			
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C	<input type="radio"/> H only · <input type="radio"/> C only · None
BOOM / ARM / BKT			
Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
BKT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
<div style="border: 1px solid black; padding: 5px;"> BKT <input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER () </div> <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> Lever LONG · <input checked="" type="radio"/> WRIST </div> <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> Multi <input checked="" type="radio"/> MULTI · 2 · NO </div> <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> ARM-CRANE <input checked="" type="radio"/> YES · NO </div> <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> BLADE <input checked="" type="radio"/> YES · NO </div> <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> OFFSET YES · <input checked="" type="radio"/> NO </div> <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> OFFSET Cylinder FAIR · Attn </div> <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> Piping <input checked="" type="radio"/> YES · NO Breaker only <input checked="" type="radio"/> Multi </div>	
COMMENT	
<div style="border: 1px solid black; padding: 5px;"> RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) </div>	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。