

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |  |      |        |                   |         |
|-----------------|--|------|--------|-------------------|---------|
| INSPECTION DATE | 2024/10/28                             | MAKE | KUBOTA | MODEL             | U-20-3A |
| SERIAL          | KBCBZ46AHL3H51788                      |      | STAMP  | KBCBZ46AHL3H51788 |         |
| HR METER        | 943                                    | HR   | YEAR   | YR                |         |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE   | 250G PADS         |         |

|                                  |   |                            |
|----------------------------------|---|----------------------------|
| <b>ENGINE : MODEL</b>            | <b>S/N</b>  | 1LP1227                    |
| Oil leakage                      | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Blow-By                          | <input checked="" type="radio"/> FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Oil                              | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Exhaust Color                    | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| US EPA                           | YES · <input checked="" type="radio"/> NO                           |                            |
| <b>MAIN PUMP</b>                 |   |                            |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Oil leakage                      | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Power                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| <b>COOLING SYSTEM</b>            |   |                            |
| Radiator                         | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Oil Cooler                       | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| <b>OPERATING SYSTEM</b>          |   |                            |
| Swing                            | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Travel                           | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| <b>INTERIOR See Photos. 写真参照</b> |   |                            |
| Operator's Seat                  | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Inside Cover                     | FAIR · Attn   |                            |
| Glasses                          | FAIR · Attn   |                            |
| AirCon                           | A/C · H/C · H only · C only · <input checked="" type="radio"/> None |                            |
| <b>BOOM / ARM / BKT</b>          |   |                            |
| Boom                             | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Boom Cylinder                    | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Arm                              | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| Arm Cylinder                     | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| BKT                              | <input checked="" type="radio"/> FAIR · Attn                        |                            |
| BKT Cylinder                     | <input checked="" type="radio"/> FAIR · Attn                        |                            |

|  |  |   |
|--|--|---|
| <b>UNDERCARRIAGE :</b>   | See Photos. 写真参照   |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |  | 4   |
| <b>COMMENT</b>   |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
| BKT  | <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( ) |   |
| Lever  | LONG · <input checked="" type="radio"/> WRIST                                |   |
| Multi  | <input checked="" type="radio"/> MULTI · 2 · NO                              |   |
| ARM-CRANE  | YES · <input checked="" type="radio"/> NO                                    |   |
| BLADE  | <input checked="" type="radio"/> YES · NO                                    |   |
| OFFSET   | YES · <input checked="" type="radio"/> NO                                    |   |
| OFFSET Cylinder  | FAIR · Attn  |   |
| Piping   | <input checked="" type="radio"/> YES · NO                                    | Breaker only · <input checked="" type="radio"/> Multi |
| <b>COMMENT</b>   |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
|  |  |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |  | 4   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。