

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/10/29	MAKE	MOROOKA	MODEL	MFD-20
SERIAL	093340		STAMP	093340	
HR METER	1665	HR	Odometer	-	km YEAR YR
CAB/CNP	CAB / <u>CNP</u> / NONE		TIRE SIZE	-	
MAX LIFTING HEIGHT	3.0	m	<u>VIEW</u> MONO	FORK LENGTH	1050 mm
FORK SPEC					

ENGINE : MODEL	V2403 S/N	
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	<u>YES</u> · NO	
OPERATION PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<u>PS</u> · DD	
Transmission	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
FOOT BRAKE	<u>FAIR</u> · Attn	
PARKING BRAKE	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<u>FAIR</u> · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
HYDRAULICS		
MAST Cylinder	<u>FAIR</u> · Attn	
TILT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
SHOE: 350R	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。