

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2024/10/3	MAKE	KOMATSU	MODEL	LC785-6
SERIAL No.	PLATE : 31205	STAMP	31205		
HR METER	5601	HR	SHOE	450G PADS	YEAR YR

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1	
Travel	<input type="radio"/> FAIR · Attn	
<b>BOOM</b>		
MAIN BOOM		
BOOM TOTAL		
TOP SHEAVE	YES · <input checked="" type="radio"/> NO	
JIB		
TOWER		

<b>INTERIOR</b>		<b>See Photos. 写真参照</b>
Operator's Seat	<input type="radio"/> FAIR · Attn	破れあり CUTS
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>UNDERCARRIAGE : See Photos. 写真参照</b>		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
<b>COMMENT</b>		
WEIGHT		
		-
HOOK		
		4.9t
LIFTER		
		YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>		
5段ブーム 5-SECTION BOOM		
CAB		
EPA		
荷重計表示不良 LOAD INDICATOR: MALFUNCTION TO DISPLAY		
過巻不良 OVERWINDING PREVENTION: MALFUNCTION		
*1 右走行モーター油汚れあり RIGHT TRAVEL MOTOR: OIL STAINS		
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>		
		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。