

**INSPECTION SHEET 検品書  
FORK LIFT フォークリフト**

INSPECTION DATE	2024/10/11	MAKE	TOYOTA	MODEL	8FD50
SERIAL	8FD50-11853			STAMP	8FD50-11853
HR METER	6017	HR	Odometer	-	km YEAR YR
CAB/CNP	<input checked="" type="radio"/> CAB / <input type="radio"/> CNP / <input type="radio"/> NONE			TIRE SIZE	F: 7.50-16 R: 7.00-12
MAX LIFTING HEIGHT	4.0	m	<input checked="" type="radio"/> VIEW	MONO	FORK LENGTH 1210 mm
FORK SPEC					

<b>ENGINE : MODEL</b>	<b>S/N</b>
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Blow-By <input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil <input checked="" type="radio"/> FAIR · Attn	
Exhaust Color <input checked="" type="radio"/> FAIR · Attn	
US EPA YES · <input checked="" type="radio"/> NO	
<b>OPERATION PUMP</b>	
Sound <input checked="" type="radio"/> FAIR · Attn	
Oil leakage <input checked="" type="radio"/> FAIR · Attn	
Power <input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>	
Radiator <input checked="" type="radio"/> FAIR · Attn	
Oil Cooler <input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE <input checked="" type="radio"/> PS · DD	
Transmission <input checked="" type="radio"/> FAIR · Attn	
Travel <input checked="" type="radio"/> FAIR · Attn	
FOOT BRAKE <input checked="" type="radio"/> FAIR · Attn	
PARKING BRAKE <input checked="" type="radio"/> FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat <input checked="" type="radio"/> FAIR · Attn	
Inside Cover <input checked="" type="radio"/> FAIR · Attn	
Glasses <input checked="" type="radio"/> FAIR · Attn	
AirCon A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
<b>HYDRAULICS</b>	
MAST Cylinder <input checked="" type="radio"/> FAIR · Attn	
TILT Cylinder <input checked="" type="radio"/> FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
<b>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	<b>3</b>
<b>COMMENT</b>	
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	<b>3</b>

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。