

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/28	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB4361			STAMP : TR256-1079	
HR METER	21087	HR	Odometer	84364	km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR <input checked="" type="radio"/> Attn	*1
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
OPERATION PUMP		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
COOLING SYSTEM		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
OPERATING SYSTEM		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
TRANSMISSION		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	破れあり CUT
Inside Cover	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None	
COMMENT		

BOOM		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn	
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn	にじみあり OIL OOZING
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn	
JIB	YES <input checked="" type="radio"/> NO	
JIB TYPE	STD <input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO	
HOOK	25t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
OUTRIGGERS		
OUTRIGGERS	X <input checked="" type="radio"/> H	
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn	
COMMENT		
補巻: 過巻センサー不良、非常用にて作動		
OVERWINDING PREVENTION SENSOR FOR AUXILIARY HOISTING WIRE: MALFUNCTION,		
ABLE TO OPERATE WITH THE EMERGENCY MODE		
主巻ウインチモーターにじみあり WINCH MOTOR FOR MAIN WIRE: OIL OOZING		
リターダにじみあり AROUND RETARDER: OIL OOZING		
*1 E/G上部油漏れあり UPPER PART OF ENGINE: OIL LEAKING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。