

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|-----------------|------|--------------------|--------|-------------|
| INSPECTION DATE | 2024/10/25 | MAKE | KATO | MODEL | KR-10H-L II |
| SERIAL No. | PLATE : 3910751 | | STAMP : KR102-0751 | | |
| HR METER | 13200 | HR | Odometer | 132913 | km |
| TIRE SIZE | 275/80R22.5 | | YEAR | YR | |

| ENGINE : MODEL | S/N |
|----------------------------------|---|
| Oil leakage | <input type="radio"/> FAIR · Attn |
| Blow-By | <input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound | <input type="radio"/> FAIR · Attn |
| Oil | <input type="radio"/> FAIR · Attn |
| Exhaust Color | <input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 黒煙あり BLACK FUMES |
| OPERATION PUMP | |
| Sound | <input type="radio"/> FAIR · Attn |
| Oil leakage | <input type="radio"/> FAIR · Attn |
| Power | <input type="radio"/> FAIR · Attn |
| COOLING SYSTEM | |
| Radiator | <input type="radio"/> FAIR · Attn |
| Oil Cooler | <input type="radio"/> FAIR · Attn |
| OPERATING SYSTEM | |
| Computer | <input checked="" type="radio"/> OK · NG |
| Swing | <input type="radio"/> FAIR · Attn |
| Travel | <input type="radio"/> FAIR · Attn |
| TRANSMISSION | |
| Transmission | <input type="radio"/> FAIR · Attn |
| No. OF GEARS | 3 GEARS |
| No. of DRIVE WHEELS | 4 WD |
| INTERIOR See Photos. 写真参照 | |
| Operator's Seat | <input type="radio"/> FAIR · Attn |
| Inside Cover | <input type="radio"/> FAIR · Attn |
| Glasses | <input type="radio"/> FAIR · Attn |
| AirCon | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |
| COMMENT | |
| | |

| BOOM | |
|---|---|
| No. of Section | 6 SECTIONS |
| CRACK/ENFORCEMENT | <input type="radio"/> FAIR · Attn |
| DERRICKING CYL. | <input type="radio"/> FAIR · Attn |
| EXTENSION CYL. | <input type="radio"/> FAIR · Attn |
| JIB | <input checked="" type="radio"/> YES · NO |
| JIB TYPE | <input type="radio"/> STD · PWR |
| MAIN & SUB WIRE | <input checked="" type="radio"/> YES · NO |
| HOOK | 10t, BALL |
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| COMMENT | |
| リアステロロックピン抜けない | |
| REAR STEERING LOCK PIN: UNABLE TO RELEASE | |
| OUTRIGGERS | |
| OUTRIGGERS | X · <input checked="" type="radio"/> H |
| OUTRIGGERS COND. | FAIR · <input type="radio"/> Attn *1 |
| COMMENT | |
| 左Fウインカー割れあり FRONT LEFT BLINKER COVER: BROKEN | |
| *1 右ロッド傷あり RIGHT VERTICAL CYLINDER RODS: SCRATCHED | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | |
| 3 | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。