

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/2	MAKE	CAT	MODEL	320D-E
SERIAL	CAT0320DPBWZ0811? SOME LETTER: UNREADABLE		STAMP	CAT0320DPBWZ08114	
HR METER	7052 / 7051	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
<b>MAIN PUMP</b>		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	FAIR · Attn	穴あり HOLES
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	Fひびあり UPPER WINDSHIELD: CRACKED
AirCon	A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	へコミあり DENT
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
右Fキャリアローラー偏摩耗あり FRONT RIGHT CARRIER ROLLER: PARTLY MUCH WORN	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
<b>COMMENT</b>	
バックカメラ曇りあり BACK MONITOR: PARTLY NOT DISPLAYING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。