

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/3	MAKE	CAT	MODEL	312D
SERIAL	CAT0312DKFBJ00853		STAMP	CAT0312DKFBJ00853	
HR METER	6321	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR	Attn 破れあり TORN
Inside Cover	FAIR	Attn
Glasses	FAIR	Attn Fアクリル板 UPPER WINDSHIELD: ACRYLIC BOARD
AirCon	A/C	H/C · H only · C only · None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
BKT	FAIR	Attn ガタ、穴あり LOOSE, CRACKED
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
シューパッド摩耗大、剥がれ多数あり RUBBER PADS: ALMOST GONE		
BKT	STD	SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST	
Multi	MULTI · 2 · NO	
ARM-CRANE	YES · NO	
BLADE	YES · NO	
OFFSET	YES · NO	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · NO	Breaker only · Multi
COMMENT		
A/C効かない A/C: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。