

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/3	MAKE	YANMAR	MODEL	VIO70-3A
SERIAL	36229B		STAMP	36229B	
HR METER	3710	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	450G PADS	

<b>ENGINE : MODEL</b>		S/N	J0660
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	<u>YES</u> · NO		
<b>MAIN PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>OPERATING SYSTEM</b>			
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE	
Travel	<u>FAIR</u> · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<u>FAIR</u> · Attn		
Inside Cover	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn	*1	
AirCon	<u>A/C</u> · H/C · H only · C only · None		
<b>BOOM / ARM / BKT</b>			
Boom	<u>FAIR</u> · Attn	ガタあり LOOSE	
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn	ガタあり LOOSE	
Arm Cylinder	<u>FAIR</u> · Attn		
BKT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
<div style="border: 1px solid black; padding: 5px;"> <p>BKT <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )</p> <p>Lever LONG · <u>WRIST</u></p> <p>Multi <u>MULTI</u> · 2 · NO</p> <p>ARM-CRANE YES · <u>NO</u></p> <p>BLADE <u>YES</u> · NO</p> <p>OFFSET YES · <u>NO</u></p> <p>OFFSET Cylinder FAIR · Attn</p> <p>Piping YES · <u>NO</u> Breaker only · Multi</p> </div>	
<b>COMMENT</b>	
*1 左側窓コーキングあり LEFT SIDE GLASS FRAME: CAULKING	
<div style="border: 1px solid black; padding: 5px;"> <p>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</p> <p style="text-align: right;">3</p> </div>	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。