

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2024/8/19	MAKE	MAEDA	MODEL	CC1485S-1	
SERIAL No.	PLATE : 7792	STAMP	7792			
HR METER	1482	HR	SHOE	500G PADS	YEAR	YR

<b>ENGINE : MODEL</b>	4LE2	<b>S/N</b>	699110
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	

<b>OPERATION PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	

<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	

<b>OPERATING SYSTEM</b>			
Computer	<input checked="" type="radio"/> OK	NG	
Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	

<b>BOOM</b>	
MAIN BOOM	
BOOM TOTAL	
TOP SHEAVE	YES <input checked="" type="radio"/> NO
JIB	
TOWER	

<b>INTERIOR</b>	See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Inside Cover	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None	

<b>UNDERCARRIAGE :</b>	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	

<b>COMMENT</b>	
WEIGHT	-
HOOK	4.9t
LIFTER	YES <input type="radio"/> NO <input checked="" type="radio"/>

<b>COMMENT</b>	
CAB	
EPA	
5段ブーム	5-SECTION BOOM
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。