INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/10/7	MAKE	YANMAR	MODEL	V1-1A
SERIAL	12739			STAMP	NOT FOUND
HR METER	877 STOP HR	Odometer	- km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	10.0/70-12

ENGINE : MODEL	S/N 29706	
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
FOOT BRAKE	FAIR・Attn	
PARKING BRAKE	FAIR・Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	FAIR・Attn	破れあり CUTS
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
FRONT & CYLINDERS		
Arm	FAIR・Attn	
Bell crank	FAIR・Attn	
Bucket	FAIR・Attn	
Articulate	FAIR・Attn	ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING		
RIDE CONTROL	YES・NO		
ATTACHMENTS			
STD BKT	YES・OTHER		
BLADE	YES・NO	Piping for Tilt	YES・NO
COMMENT			
HRメーター故障あり HR METER: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。