

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/16	MAKE	KOMATSU	MODEL	PC78US-6N0
SERIAL	7207	STAMP		KMTPC030A0100720? SOME LETTER: UNREADABLE	
HR METER	UNREADABLE	HR	YEAR	YR	
CAB/CNP	ROPS CAB <input checked="checked" type="checkbox"/> / <input type="checkbox"/> ROPS CNP / <input type="checkbox"/> / <input type="checkbox"/> NONE		SHOE	450G PADS	

ENGINE : MODEL 4D95LE-3 S/N 103986	
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn
Blow-By	<input checked="checked" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="checked" type="radio"/> FAIR · Attn
Oil	<input checked="checked" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="checked" type="radio"/> FAIR · Attn
US EPA	<input checked="checked" type="radio"/> YES · NO
MAIN PUMP	
Sound	<input checked="checked" type="radio"/> FAIR · Attn
Oil leakage	<input checked="checked" type="radio"/> FAIR · Attn
Power	<input checked="checked" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="checked" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="checked" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Swing	<input checked="checked" type="radio"/> FAIR · Attn
Travel	<input checked="checked" type="radio"/> FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="checked" type="radio"/> FAIR · Attn
Inside Cover	<input checked="checked" type="radio"/> FAIR · Attn
Glasses	<input type="radio"/> FAIR · <input checked="checked" type="radio"/> Attn 前面下ガラスなし LOWER WINDSHIELD: MISSING
AirCon	<input checked="checked" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None
BOOM / ARM / BKT	
Boom	<input checked="checked" type="radio"/> FAIR · Attn
Boom Cylinder	<input checked="checked" type="radio"/> FAIR · Attn
Arm	<input checked="checked" type="radio"/> FAIR · Attn
Arm Cylinder	<input checked="checked" type="radio"/> FAIR · Attn
BKT	<input type="radio"/> FAIR · <input checked="checked" type="radio"/> Attn 穴あきあり MUCH HOLES
BKT Cylinder	<input checked="checked" type="radio"/> FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	<input checked="checked" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER()
Lever	LONG · <input checked="checked" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="checked" type="radio"/> NO
ARM-CRANE	YES · <input checked="checked" type="radio"/> NO
BLADE	<input checked="checked" type="radio"/> YES · NO
OFFSET	YES · <input checked="checked" type="radio"/> NO
OFFSET Cylinder	<input checked="checked" type="radio"/> FAIR / <input type="radio"/> Attn
Piping	YES · <input checked="checked" type="radio"/> NO Breaker only · Multi
COMMENT	
A/Cあるが風が出ない A/C: NOT BLOWING AIR	
液晶画面暗くてほぼ見えない	
MONITOR: VERY BLURRED (ALMOST UNREADABLE)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。