

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/15	MAKE	CAT	MODEL	312
SERIAL	7DK01629		STAMP	7DK01629	
HR METER	4703 STOP	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
<b>MAIN PUMP</b>		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
<b>INTERIOR</b> See Photos. 写真参照		
Operator's Seat	FAIR · Attn	破れあり HUGE CUT
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*1
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
足周り石灰付着あり LIME STAINS	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
<b>COMMENT</b>	
HRメーター故障あり HR METER: MALFUNCTION	
ドア内側から開かない DOOR: UNABLE TO OPEN FROM INSIDE	
*1 左シリンダー油漏れあり LEFT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。