INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2024/10/7	MAKE	KOMATSU	MODEL	D31PLL-16
SERIAL	29379			STAMP	D31P16-29379
HR METER	E4147 HR	SHOE	1050LGP	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	DIFF. STEERING YES・NO
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR・Attn	
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	右脇ひび割れ大 RIGHT SIDE GLASS: CRACKED
AirCon	A/C・H/C・H only・C only・None	
BLADE & CYLINDERS		
BLADE	FAIR・Attn	
CYLD.(R)	FAIR・Attn	
CYLD.(L)	FAIR・Attn	油漏れ小 OIL LEAKING
TILT CYLD	FAIR・Attn	
ANGLE CYLD	FAIR・Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
COMMENT			
左側ピンブッシュ割れあり SOME LEFT PIN BUSHES: BROKEN			
Ripper	MULTI・S/S	Shanks	PCS
Ripper CYLD.	FAIR・Attn		
EQUALIZER BAR	FAIR・Attn		
COMMENT			
HRメーター不良 HR METER: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。