

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/11	MAKE	HITACHI	MODEL	ZX75US-5B
SERIAL	HCMDEPA0J00072560		STAMP	HCMDEPA0J00072560	
HR METER	2717	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Blow-By	<input checked="" type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil	<input checked="" type="radio"/> FAIR	Attn
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn
US EPA	<input checked="" type="radio"/> YES · NO	
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Power	<input checked="" type="radio"/> FAIR	Attn
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR	Attn
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR	Attn ガタあり SWING: LOOSE
Travel	<input checked="" type="radio"/> FAIR	Attn
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn
Inside Cover	<input checked="" type="radio"/> FAIR	Attn
Glasses	<input checked="" type="radio"/> FAIR	Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR	Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn
Arm	<input checked="" type="radio"/> FAIR	Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn
BKT	<input checked="" type="radio"/> FAIR	Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only <input checked="" type="radio"/> Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。