

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/22	MAKE	CAT	MODEL	314FCR
SERIAL	CAT0314FHRAF10394		STAMP	CAT0314FHRAF10394	
HR METER	3826 / 3828	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL C4.4 S/N	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	<input checked="" type="radio"/> YES · NO
MAIN PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	<input checked="" type="radio"/> FAIR · Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn
Arm	<input checked="" type="radio"/> FAIR · Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn
BKT	<input checked="" type="radio"/> FAIR · Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。