

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/17	MAKE	CAT	MODEL	308E2CR-E
SERIAL	CAT0308ECPC800199		STAMP	CAT0308ECPC800199	
HR METER	2789	HR	YEAR	YR	
CAB/CNP	ROPS CAB	/ CAB / ROPS CNP / CNP / NONE	SHOE	450G PADS	

ENGINE : MODEL	C3.3B	S/N
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Blow-By	<input checked="" type="radio"/> FAIR	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil	<input checked="" type="radio"/> FAIR	Attn
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn
US EPA	<input checked="" type="radio"/> YES	NO
MAIN PUMP		
Sound	<input checked="" type="radio"/> FAIR	Attn
Oil leakage	<input checked="" type="radio"/> FAIR	Attn
Power	<input checked="" type="radio"/> FAIR	Attn
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR	Attn
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn
OPERATING SYSTEM		
Swing	<input checked="" type="radio"/> FAIR	Attn
Travel	<input checked="" type="radio"/> FAIR	Attn
INTERIOR See Photos. 写真参照		
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn
Inside Cover	<input checked="" type="radio"/> FAIR	Attn
Glasses	<input checked="" type="radio"/> FAIR	Attn
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None
BOOM / ARM / BKT		
Boom	<input checked="" type="radio"/> FAIR	Attn
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn
Arm	<input checked="" type="radio"/> FAIR	Attn
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn
BKT	<input checked="" type="radio"/> FAIR	Attn
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
.....	
.....	
.....	
.....	
BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	<input checked="" type="radio"/> MULTI · 2 · NO
ARM-CRANE	<input checked="" type="radio"/> YES · NO フック欠 NO HOOK
BLADE	<input checked="" type="radio"/> YES · NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · <input checked="" type="radio"/> NO Breaker only · Multi
COMMENT	
.....	
.....	
.....	
.....	
.....	
.....	
.....	
.....	
.....	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。