INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/21	MAKE	KOMATSU	MODEL	LW250-5
SERIAL No.	PLATE : 50345		STAMP : L003-50345		
HR METER	2456 HR		Odometer	15238 km	
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N		
Oil leakage	FAIR · (Attn)	E/G下部にじみあり BOTTOM: OIL OOZING
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	FAIR · (Attn)	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	3 GEARS	
No, of DRIVE WHEELS	4 WD	
INTERIOR See Photos. 写真参照		
Operator's Seat	(FAIR) · Attn	
Inside Cover	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM		
No. of Section	5 SECTIONS	
CRACK/ENFORCEMENT	(FAIR) · Attn	
DERRICKING CYL.	(FAIR) · Attn	
EXTENSION CYL.	(FAIR) · Attn	
JIB	(YES) · NO	
JIB TYPE	STD · (PWR)	
MAIN & SUB WIRE	(YES) · NO	
HOOK	26t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
リアステ不良、ピン抜けない		
REAR STEERING: MALFUNCTION, LOCK PIN: UNABLE TO RELEASE		
OUTRIGGERS		
OUTRIGGERS	(X) · H	
OUTRIGGERS COND.	(FAIR) · Attn	
COMMENT		
噴射ポンプ燃料漏れあり INJECTION PUMP: OIL LEAKING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。