

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/24	MAKE	HITACHI	MODEL	ZX670LC-6
SERIAL	HCMJBKA0V00060135		STAMP	HCMJBKA0V00060135	
HR METER	11132	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <b>CAB</b> / ROPS CNP / CNP / NONE		SHOE	650G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<b>FAIR</b> · Attn	
Blow-By	<b>FAIR</b> · <b>Attn</b>	A LITTLE <b>MIDDLE</b> SEVERE
Sound	<b>FAIR</b> · Attn	
Oil	<b>FAIR</b> · Attn	
Exhaust Color	<b>FAIR</b> · Attn	
US EPA	YES · <b>NO</b>	
<b>MAIN PUMP</b>		
Sound	<b>FAIR</b> · Attn	
Oil leakage	<b>FAIR</b> · Attn	
Power	<b>FAIR</b> · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<b>FAIR</b> · Attn	
Oil Cooler	<b>FAIR</b> · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<b>FAIR</b> · Attn	
Travel	<b>FAIR</b> · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<b>FAIR</b> · Attn	
Inside Cover	<b>FAIR</b> · Attn	
Glasses	<b>FAIR</b> · Attn	
AirCon	<b>A/C</b> · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	<b>FAIR</b> · Attn	
Boom Cylinder	<b>FAIR</b> · Attn	
Arm	<b>FAIR</b> · Attn	
Arm Cylinder	<b>FAIR</b> · Attn	
BKT	<b>FAIR</b> · Attn	
BKT Cylinder	<b>FAIR</b> · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
<b>RUST</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	<b>3</b>
<b>COMMENT</b>	
BKT	STD / SLOPE / NARROW / SKELETON / <b>OTHER</b> (MAGNET)
Lever	LONG · <b>WRIST</b>
Multi	MULTI · 2 · <b>NO</b>
ARM-CRANE	YES · <b>NO</b>
BLADE	YES · <b>NO</b>
OFFSET	YES · <b>NO</b>
OFFSET Cylinder	FAIR · Attn
Piping	YES · <b>NO</b> Breaker only · Multi
<b>COMMENT</b>	
MAGNET MAKE: SUMITOMO LECH20F7-AS-M200037	
発電機 GENERATOR MAKE: DENYO DCA-60ESI2-3950587	
付属品:カバー類 SOME COVERS AS SPARE	
<b>RUST of BODY</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
<b>3</b>	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。