

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/10/10	MAKE	KOMATSU	MODEL	WA100-8
SERIAL	90102		STAMP	WA138-90102	
HR METER	12334	HR	Odometer	32523	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	12.00-24	
YEAR					YR

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES · <input checked="" type="radio"/> NO
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<input checked="" type="radio"/> PS · DD
Transmission	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり HUGE CUTS
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn F割れあり WINDSHIELD: CRACKED
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	<input checked="" type="radio"/> FAIR · Attn ロングアーム LONG ARM
Bell crank	<input checked="" type="radio"/> FAIR · Attn
Bucket	<input checked="" type="radio"/> FAIR · Attn ガタあり LOOSE
Articulate	<input checked="" type="radio"/> FAIR · Attn ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
左タイヤ: 摩耗大、ボルト刺さりあり	
FRONT LEFT TIRE: TOO MUCH WORN, BOLT: STUCK FRONT LEFT TIRE	
エアボスタイヤ AIR BOSS TIRES	
STEERING TYPE <input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING	
RIDE CONTROL	<input checked="" type="radio"/> YES · NO
ATTACHMENTS	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
COMMENT	
右サイドカバー変形あり、閉まらない	
RIGHT SIDE COVER: DEFORMED, UNABLE TO SHUT	
バリエブルシフトコントロールダイヤル欠、変速できない	
VARIABLE SHIFT CONTROL KNOB: MISSING (UNABLE TO CHANGE GEARS)	
L03、L01表示あり "L03" & "L01" ERRORS DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。