

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2024/10/21	MAKE	HITACHI SUMITOMO	MODEL	SCX2000-2C3
SERIAL No.	PLATE : SC200-7085		STAMP	SC200-7085	
HR METER	9132	HR	SHOE	1100FLAT	YEAR YR

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	OK · NG ML未確認 NOT CHECKED
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
BOOM	
MAIN BOOM	TOP, BOTTOM, 9m × 3, 6m × 1, 3m × 1
BOOM TOTAL	51m
TOP SHEAVE	<input checked="" type="radio"/> YES · NO
JIB	
TOWER	

INTERIOR	See Photos. 写真参照
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn 天窓ガラスひび割れあり SKYLIGHT: CRACKED
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
WEIGHT	11, LOWER WEIGHT × 2
HOOK	200t/125t, 80t, 35t, BALL, HANGER SHEAVE
LIFTER	<input checked="" type="radio"/> YES · NO
COMMENT	
@NARITA YARD	
BOOM: TOP, BOTTOM, 6m × 1, 3m × 1	
@SAKURA YARD	
BOOM: 9m × 3	
HOOK: 200t/125t, 35t, BALL	
LOWER WEIGHT × 2	
A SET OF HANGER SHEAVE, AUXILIARY HOISTING LIMIT SWITCH	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。