

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |  |      |           |                  |          |
|-----------------|--|------|-----------|------------------|----------|
| INSPECTION DATE | 2024/10/3                              | MAKE | CAT       | MODEL            | 308DCR-2 |
| SERIAL          | CAT0308DHSA00980                       |      | STAMP     | CAT0308DHSA00980 |          |
| HR METER        | 9528 / 7240 + 2300                     | HR   | YEAR      | YR               |          |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE | SHOE | 450G PADS |                  |          |

| ENGINE : MODEL   | S/N   |
|--|---|
| Oil leakage <input checked="" type="radio"/> FAIR · Attn     |   |
| Blow-By <input checked="" type="radio"/> FAIR · Attn         | A LITTLE · MIDDLE · SEVERE  |
| Sound <input checked="" type="radio"/> FAIR · Attn           |   |
| Oil <input checked="" type="radio"/> FAIR · Attn             |   |
| Exhaust Color <input checked="" type="radio"/> FAIR · Attn   |   |
| US EPA   | YES · <input checked="" type="radio"/> NO                           |
| MAIN PUMP  |   |
| Sound <input checked="" type="radio"/> FAIR · Attn           |   |
| Oil leakage <input checked="" type="radio"/> FAIR · Attn     |   |
| Power <input checked="" type="radio"/> FAIR · Attn           |   |
| COOLING SYSTEM   |   |
| Radiator <input checked="" type="radio"/> FAIR · Attn        |   |
| Oil Cooler <input checked="" type="radio"/> FAIR · Attn      |   |
| OPERATING SYSTEM   |   |
| Swing <input checked="" type="radio"/> FAIR · Attn           | ガタあり SWING: LOOSE   |
| Travel <input checked="" type="radio"/> FAIR · Attn          |   |
| INTERIOR See Photos. 写真参照                                    |   |
| Operator's Seat <input checked="" type="radio"/> FAIR · Attn |   |
| Inside Cover <input checked="" type="radio"/> FAIR · Attn    |   |
| Glasses <input checked="" type="radio"/> FAIR · Attn         |   |
| AirCon   | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |
| BOOM / ARM / BKT   |   |
| Boom <input checked="" type="radio"/> FAIR · Attn            |   |
| Boom Cylinder <input checked="" type="radio"/> FAIR · Attn   |   |
| Arm <input checked="" type="radio"/> FAIR · Attn             | ガタあり LOOSE  |
| Arm Cylinder <input checked="" type="radio"/> FAIR · Attn    |   |
| BKT <input checked="" type="radio"/> FAIR · Attn             |   |
| BKT Cylinder <input checked="" type="radio"/> FAIR · Attn    |   |

| UNDERCARRIAGE : See Photos. 写真参照   |   |
|--|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                     | 3   |
| COMMENT  |   |
|  |   |
|  |   |
|  |   |
|  |   |
| BKT <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( ) |   |
| Lever  | LONG · <input checked="" type="radio"/> WRIST   |
| Multi  | <input checked="" type="radio"/> MULTI · 2 · NO   |
| ARM-CRANE  | YES · <input checked="" type="radio"/> NO   |
| BLADE  | <input checked="" type="radio"/> YES · NO   |
| OFFSET   | YES · <input checked="" type="radio"/> NO   |
| OFFSET Cylinder  | FAIR · Attn   |
| Piping   | <input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi |
| COMMENT  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
|  |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)             | 4   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。