

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/25	MAKE	SUMITOMO	MODEL	SH200-3
SERIAL	200Z3-1640		STAMP	200Z3-1640	
HR METER	8839	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	600G		

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR	Attn
Blow-By	<input type="radio"/> FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR	Attn
Oil	<input type="radio"/> FAIR	Attn
Exhaust Color	<input type="radio"/> FAIR	Attn
US EPA	YES	<input type="radio"/> NO

MAIN PUMP	
Sound	<input type="radio"/> FAIR
Oil leakage	<input type="radio"/> FAIR
Power	<input type="radio"/> FAIR

COOLING SYSTEM	
Radiator	<input type="radio"/> FAIR
Oil Cooler	<input type="radio"/> FAIR

OPERATING SYSTEM	
Swing	<input type="radio"/> FAIR <input checked="" type="radio"/> Attn スイベルにじみあり SWIVEL: OIL Oozing
Travel	<input type="radio"/> FAIR

INTERIOR See Photos. 写真参照	
Operator's Seat	<input type="radio"/> FAIR
Inside Cover	<input type="radio"/> FAIR
Glasses	<input type="radio"/> FAIR
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

BOOM / ARM / BKT	
Boom	<input type="radio"/> FAIR <input checked="" type="radio"/> Attn クラックあり CRACKED
Boom Cylinder	<input type="radio"/> FAIR
Arm	<input type="radio"/> FAIR
Arm Cylinder	<input type="radio"/> FAIR
BKT	<input type="radio"/> FAIR
BKT Cylinder	<input type="radio"/> FAIR

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT
トラックローラー不良 SOME TRACK ROLLERS: MALFUNCTION
キャリアローラー破損あり RIGHT CARRIER ROLLERS: BROKEN

BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
-----	--

Lever	LONG · <input checked="" type="radio"/> WRIST
-------	---

Multi	MULTI · 2 · <input checked="" type="radio"/> NO
-------	---

ARM-CRANE	YES · <input checked="" type="radio"/> NO
-----------	---

BLADE	YES · <input checked="" type="radio"/> NO
-------	---

OFFSET	YES · <input checked="" type="radio"/> NO
--------	---

OFFSET Cylinder	FAIR · Attn
-----------------	-------------

Piping	<input checked="" type="radio"/> YES · NO Breaker only <input checked="" type="radio"/> Multi
--------	---

COMMENT
A/Cベルト欠 A/C: NO BELT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。