

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/7	MAKE	HITACHI	MODEL	ZX135US-3
SERIAL	HCM1R400T00083125		STAMP	HCM1R400T00083125	
HR METER	6115	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	500G		

ENGINE : MODEL	4JJ1	S/N	115456	UNDERCARRIAGE :	See Photos. 写真参照
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE		COMMENT	
Sound	<input checked="" type="radio"/> FAIR · Attn				
Oil	<input checked="" type="radio"/> FAIR · Attn				
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn				
US EPA	<input checked="" type="radio"/> YES · NO				
MAIN PUMP				BKT	<input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ()
Sound	<input checked="" type="radio"/> FAIR · Attn			Lever	LONG · <input checked="" type="radio"/> WRIST
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			Multi	MULTI · 2 · <input checked="" type="radio"/> NO
Power	<input checked="" type="radio"/> FAIR · Attn			ARM-CRANE	YES · <input checked="" type="radio"/> NO
COOLING SYSTEM				BLADE	YES · <input checked="" type="radio"/> NO
Radiator	<input checked="" type="radio"/> FAIR · Attn			OFFSET	YES · <input checked="" type="radio"/> NO
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn			OFFSET Cylinder	FAIR · Attn
OPERATING SYSTEM				Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
Swing	<input checked="" type="radio"/> FAIR · Attn			COMMENT	
Travel	<input checked="" type="radio"/> FAIR · Attn			*1 メッキ剥がれ、傷あり COATING: PEELED, SCRATCHED	
INTERIOR See Photos. 写真参照					
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn				
Inside Cover	<input checked="" type="radio"/> FAIR · Attn				
Glasses	<input checked="" type="radio"/> FAIR · Attn				
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None				
BOOM / ARM / BKT					
Boom	<input checked="" type="radio"/> FAIR · Attn				
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn				
Arm	<input checked="" type="radio"/> FAIR · Attn				
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn				
BKT	FAIR · <input checked="" type="radio"/> Attn	ピンガタあり PIN: LOOSE			
BKT Cylinder	FAIR · <input checked="" type="radio"/> Attn	*1		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。