

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/8	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD1431		STAMP : TR120-1403		
HR METER	11330	HR	Odometer	118521	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	<input type="radio"/> FAIR	Attn	
Blow-By	<input type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR	Attn	
Oil	<input type="radio"/> FAIR	Attn	
Exhaust Color	<input type="radio"/> FAIR	Attn	

OPERATION PUMP

Sound	<input type="radio"/> FAIR	Attn	
Oil leakage	<input type="radio"/> FAIR	Attn	
Power	<input type="radio"/> FAIR	Attn	

COOLING SYSTEM

Radiator	<input type="radio"/> FAIR	Attn	
Oil Cooler	<input type="radio"/> FAIR	Attn	

OPERATING SYSTEM

Computer	<input checked="" type="radio"/> OK	NG	
Swing	<input type="radio"/> FAIR	Attn	
Travel	<input type="radio"/> FAIR	Attn	

TRANSMISSION

Transmission	<input type="radio"/> FAIR	Attn	
No. OF GEARS	3	GEARS	
No. of DRIVE WHEELS	4	WD	

INTERIOR See Photos. 写真参照

Operator's Seat	<input type="radio"/> FAIR	Attn	破れあり CUT
Inside Cover	<input type="radio"/> FAIR	Attn	
Glasses	<input type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	<input type="radio"/> FAIR	Attn	
DERRICKING CYL.	<input type="radio"/> FAIR	<input checked="" type="radio"/> Attn	ロッド傷あり ROD: SCRATCHED
EXTENSION CYL.	<input type="radio"/> FAIR	Attn	
JIB	<input checked="" type="radio"/> YES	NO	
JIB TYPE	<input checked="" type="radio"/> STD	PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES	NO	
HOOK	12t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

OUTRIGGERS

OUTRIGGERS	<input checked="" type="radio"/> X	H	
OUTRIGGERS COND.	<input type="radio"/> FAIR	Attn	

COMMENT

ロータリーから水漏れあり ROTARY: WATER LEAKING 過巻不良(解除で作動確認)	
OVERWINDING PREVENTION: MALFUNCTION (NEED TO CUT THE COMPUTER TO OPERATE)	

COMMENT

エア一漏れ大 MUCH AIR LEAKING	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。